

# Oil Field Environmental Incident Summary

**Incident:** 20131220112357      **Date/Time of Notice:** 12/20/2013 10:24

**Responsible Party:** HESS Corp.

**Well Operator:** HESS CORPORATION

**Well Name:** EN-URAN S 154-93-1312H-2

**Field Name:** ROBINSON LAKE

**Well File #:** 22858

**Date Incident:** 12/19/2013      **Time Incident:** 1:15

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 93

**Sec:** 13

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Brett Williamson

**Received By:**

**Contact Person:** Kerry Burns  
3015 16TH ST SW STE 20  
MINOT, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	5	barrels	4	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

30 foot diameter circle

**Potential Environmental Impacts:**

Soil contamination

**Action Taken or Planned:**

Power Fuels is removing and disposing of the contaminated soil.

**Wastes Disposal Location:** Basic Solids Disposal

**Agencies Involved:**

**Updates**

---

**Date:** 12/20/2013 **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident report, this spill impacted areas off of location. Followup necessary.

---

**Date:** 12/23/2013 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Site inspections revealed that entirety of spill remained on location. NDIC retains oversight. However, it was recommended to the company man that more cleanup be done on location.